




## MFT4-50 Repair Kit

- (1) Bimetal Element Part Number 5615
- (1) Float Assembly Part Number 1286
- (1) Valve Assembly Part Number 0205
- (1) Valve Seat Part Number 1603L
- (1) Cover Gasket Part Number M2302
- (1) Strainer Part Number M0351
- \* (2) Pivot Pin Plug Part Number 1192
- \* (2) Pivot Plug Washer Part Number 2001

\*Optional Parts



\*Tools required for repair:  
Stem Key Part Number L99001

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance