




MFT3-200 Repair Kit

- (1) Bimetal Element Part Number M5613
- (1) Float Assembly Part Number 1289
- (1) Valve Assembly Part Number 0207
- (1) Valve Seat Part Number 1609L
- (1) Cover Gasket Part Number M6100-W
- (1) Strainer Part Number M6300
- * (2) Pivot Pin Plug Part Number 1191
- * (2) Pivot Pin Washers Part Number 2001

*Optional Parts



*Tools required for repair:
Stem Key Part Number L99001

Velan recommends setting trap with digital calibrator, please call the number listed below if you require assistance